## FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP. 1-22-80

Section I

DMS 2112-3635 Ty.I, CLASSI

U.S. Paint Division - Grow Group, Incorporated

831 S. 21st Street\_ STREET ADDRESS

CITY. STATE. AND ZIPCODE St. Louis, Missouri 63103

EMERGENCY TELEPHONE NO.

(314) 621-0525

PRODUCT CLASS

Modified Polyester Resin

TRADE NAME

Alumigrip Aluminum Enamel MANUFACTURERS CODE IDENTIFICATION 92-A- 41

(61009)

ENTS

INGREDIENT		Volume PERCENT	T PPM	LV mg/M³	LEL	VAPOR PRESSURE in mm Hg
	Ethyl Acetate Methyl Ethyl Ketone Toluene 2-Ethoxy Ethyl Acetate	14.0 3.0 5.0 42.0	400 200 100 100	1440 590 375 540	2.2 1.8 1.27 1.7	76.0 71.2 38.0 1.2
) *Co-React	Polyester Resin Aluminum Pigment Additives  1 to 1 by Volume with 92-C-39	29.0 2.0 5.0	N.A. N.A. N.A.			

## Section III - PHYSICAL DATA

**BOILING RANGE** 167 to 329° F

VAPOR DENSITY

X HEAVIER

LIGHTER, THAN AIR

**EVAPORATION RATE** 

FASTER | X | SLOWER, THAN ETHER

PERCENT VOLATILE BY VOLUME

64.0

WEIGHT PER

9.0

## Section IV — FIRE AND EXPLOSION HAZARD DATA

Combustible Liquid 100°F. -200°F. DOT CATEGORY Flammable Liquid 20°F.-100°F. 🔯

**FLASH POINT** 

1.27 LEL

Non Flammable

extinguishing media Dry chemical or foam

unusual fire and explosion hazards. Do not expose to spark or open flame

SPECIAL FIRE FIGHTING PROCEDURES

"This material does not contain intentionally added ingredients which are based on compounds of Antimony, Arsenic, Cadmium, Lead, Mercury, Selenium, or Water Soluble Barium."

Section V — HEALTH HAZARD DATA
THRESHOLDLIMIT VALUE 100 to 400 PPM
EFFECTS OF OVEREXPOSURE Eye & upper respiratory irritant
$\mathcal{L}_{\mathcal{L}}$
EMERGENCY AND FIRST AID PROCEDURES If exposed to excess vapor, remove to fresh air and seek medical attention. If splashed on skin or in eyes, flush with large amounts of water and seek immediate medical attention.
Section VI — REACTIVITY DATA
STABILITY UNSTABLE STABLE CONDITIONS TO AVOID Excess heat or oxidizing material
INCOMPAINDICTY (Materials to avoid)
HAZARDOUS DECOMPOSITION PRODUCTS
HAZARDOUS POLYMERIZATION MAY OCCUR X WILL NOT OCCUR CONDITIONS TO AVOID
Section VII — SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Affected area should be treated with an absorbing compound and then material placed in a tightly close container.  WASTE DISPOSAL METHOD In accordance with local, state, and federal environmental control regulation
Section VIII — SPECIAL PROTECTION INFORMATION
RESPIRATORY PROTECTION Bureau of Mines approved mask for removal of particulate matter and charcoa base for removal of solvent vapor.
VENTILATION Sufficient to keep air supply above threshold limit values.
PROTECTIVE GLOVES Rubber or Plastic EYE PROTECTION Goggles
OTHER PROTECTIVE EQUIPMENT Hypersensitive persons should use protective creams.
Section IX — SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Keep away from heat, sparks and flames.
OTHER PRECAUTIONS